

LOW THERMAL MASS HEATED FUS Roland Boss 10007748-1 2/3 124 211 126 -202 210 FIG. 2 -201 203 205 206 204*-*203 110 209-**~125** -207 124 208 211 126 210 -202 -201 203 FIG. 3 204 110 203 302 **~**125 209 303 205 301 206 124 211 401 -202 -201 402-405 110 -203 302 **~**125 209 FIG. 4 404 205 403

206

LOW THERMAL MASS HEATED FUSION Roland Boss 10007748-1 3/3




FIG. 6

